

PROJECT SUMMARY SHEET

Title	Rigless Leak Seal Job
Client	Seplat Petroleum Development Company Plc.
Start Date	December 2014
End Date	January 2015
Job Number	CS1406003
Scope Highlights	<p>Rigless repair of control line leak causing well to shut in production periodically.</p> <p>Held coordination meeting, rigged-up equipment at well site. Leak tested surface equipment to isolation valves at wellhead. Took control of relevant well components and operate wellhead valves as necessary to perform operation. Pressurized/de-pressurized system to run diagnostics. Injected sealant. Pressure test okay. Rigged down and handed over well.</p> <p>Control line leak fully healed.</p>

